Tel: +238 2412502
Fax: +238 2413264
Email: sgia@asa.cv
AFTN: GVACYOYX

REPUBLIC OF CABO VERDE

AERONAUTICAL INFORMATION SERVICE
AMILCAR CABRAL INTERNATIONAL AIRPORT
SAL ISLAND – CABO VERDE

AIP SUP 06/2026

Publication: **14 AUG 2026**
Effective from: **14 AUG 2026**
Effective to: **11 NOV 2026**

GVSV AD 2.30 – OBSTACLE LIGHTS UNSERVICEABLE – SÃO VICENTE / CESÁRIA ÉVORA AIRPORT (GVSV)

1. Purpose

The purpose of this AIP Supplement is to inform aircraft operators that the obstacle lights **LGT05** and **LGT12**, depicted on the Visual Approach Chart – GVSV AD 2-30, are unserviceable.

This AIP Supplement replaces NOTAM A0024/26

2. Operational Information

Obstacle lights **LGT05** and **LGT12** shown on the Visual Approach Chart – GVSV AD 2-30 are unserviceable.
Pilots are advised to exercise caution, particularly during night operations and periods of reduced visibility.

3. Validity

This AIP Supplement is effective from **14 AUG 2026** and will remain in force until **11 NOV 2026** or until the obstacle lights are restored to normal operation, **whichever occurs first**.

REF: AIP CABO VERDE, GVSV AD 2-30 – Visual Approach Chart